





Bell Mounting Assembly





This is how the footers are made. In our climate, it is desirable not to set a wooden beam directly into the ground because the dampness of the soil will inevitably cause the beam to rot.

